

## How to assemble the External Hood for TKS 60

---

**Introduction** The External Hood for TKS 60 is delivered as a kit and needs to be assembled before it can be mounted on the wall. This instruction describes how you do this.

---

**Parts included** The following parts are included in the kit:


- 5 Pcs. sheet metal plates
- 9 Pcs. Ø4x12, PH, T20, Hardened, FZB
- 2 Meter 2x8 mm Weather strip
- 11 screws Ø4,8X32 mm
- 11 screws Ø4,8X38 mm
- 11 Rawplugs for wall mounting Weather Strip for wall

---


**Tools** Standard screwdrivers are needed including torx screwdrivers.

---

**Completed assembly** This shows the how the assembled hood is placed:



**Procedure step 1** Follow this procedure to assemble the External Hood:  
Place the grill on the bottom sheet metal




*Continued overleaf*


## How to assemble the External Hood for TKS 60, *continued*

---

### Step 2



### Step 3




### Step 4

Place sheet metal plates as shown



### Step 5

Grab the assembled sheet metal plates from both sides and put them together




## How to assemble the External Hood for TKS 60, *continued*

---

### Step 6



Add 9 Screw's  
from inside!  
**Max 2Nm**



### Step 7

Attach the weather strip to  
the hood

The hood is now ready for  
wall mounting

For cutout in the wall, see  
TKS manual.

